



VOLKSWAGEN CC: 1FFR248

Vinnumber:	WVWZZZ3CZDE570314	Versionname:	CC BMT 136PK
First Registrationdate:	17/06/2013	Fiscalpower:	
Expertise Mileage:	196806	Power Kw:	100
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3606
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	235/40/18/95 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	No	Jack	Yes
-------------	-----------	------	------------

Total cost ex VAT	1947,30
-------------------	----------------

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------







Spare wheel, Missing, E - Replace 196,80



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Xenon headlight L, Scratch(es), E - Replace 696,00



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Window F L door, Scratch(es), E - Replace 168,00



Boot carpet, Stain, Cleaning 25,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

