



## SKODA OCTAVIA: 1ESH233

|                         |                          |              |  |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber:             | <b>TMBHT61Z4D2125989</b> | Versionname: | <b>OCTAVIA COMBI GTec<br/>Ambition DPF 105PK</b> |
| First Registrationdate: | <b>7/03/2013</b>         | Fiscalpower: |  |
| Expertise Mileage:      | <b>110570</b>            | Power Kw:    | <b>77</b>  |
| Bodytype:               |                          | Body color:  | <b>Black</b>                                     |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                                   |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                                 |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>  |
| Maintenance:            | <b>12/04/2017</b>        | Parking lot: | <b>3409</b>                                      |
| Maintenance:            | <b>90072</b>             |              |  |
| Maintenance:            | <b>OK</b>                |              |  |
| Battery functioning:    | <b>Yes</b>               |              |  |
| Number of doors:        | <b>5</b>                 |              |  |
| Number of seats:        | <b>5</b>                 |              |  |
| Number head rests:      | <b>5</b>                 |              |  |
| Rims summer:            | <b>Aluminium</b>         |              |  |
| Category:               | <b>Passenger Car</b>     |              |  |
| Oil level:              | <b>OK</b>                |              |  |

## Options

|                                |                              |                       |                          |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD                       |                              | Central consol F      |                          |
| GPS storage                    |                              | Luggage cover         |                          |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |                          |
| Windows electric F             |                              | Rear parking sensors  |                          |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                       |                          |
| Steering wheel multifunctional |                              |                       |                          |
| Radio multimedia               |                              |                       |                          |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                          |
| Type of Lining                 | <b>Lining leather</b>        |                       |                          |
| Type of climate control        | <b>Autom climate control</b> |                       |                          |
| Adaptive cruise control        |                              |                       |                          |

## Limited Technical Inspection

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

## Degree of wear

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|               | Re.L.                            | <b>Pirelli: 5 mm</b>     | Re.R. | <b>Pirelli: 5 mm</b>     |

## Assistance equipment

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

Total cost ex VAT 780,34

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80





Door frame R R, Scratch(es), It - Spot repair

115,56



Door R R, Bump(s), PDR - Knock out without painting

82,80



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Ignition key, Missing, E - Replace

150,00

