



VOLKSWAGEN Golf: 1FJG061			
Vinnnumber:	WVWZZZAUZEP011847	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	50048	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1031,80
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			308,20



Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80



Interior, Dirty, Cleaning 150,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

