



VOLKSWAGEN Passat: 1ERL911

Vinnnumber:	WVWZZZ3CZDE116722	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	183208	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2211
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/97 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 836,15

Seat cover F L, Stain, Cleaning 25,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display







Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display	
Door R L, Bump(s), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s), PDR - Knock out without painting	63,00
	
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror R complete, Damaged, E - Replace	168,00
	
Seat cover F R, Stain, Cleaning	25,00
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Rocker panel inner R R, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Seat cover R, Stain, Cleaning	25,00
