


**MERCEDES C: 1FUT562**

|                                    |                           |              |   |
|------------------------------------|---------------------------|--------------|---|
| Vinnnumber:                        | <b>WDD2042021G231389</b>  | Versionname: | <b>C BRE 220CDI BE Edition Avantgarde 163PK</b> |
| First Registrationdate:            | <b>30/10/2013</b>         | Fiscalpower: |   |
| Expertise Mileage:                 | <b>108166</b>             | Power Kw:    | <b>120</b>                                      |
| Bodytype:                          |                           | Body color:  | <b>Grey</b>                                     |
| Gearbox:                           | <b>MAN 6 VIT</b>          | Paint type:  | <b>Metalic</b>                                  |
| Transmission:                      | <b>Back</b>               | Rims summer: | <b>Aluminium</b>                                |
| Fueltype:                          | <b>Diesel</b>             | Oil level:   | <b>OK</b>                                       |
| Maintenance:                       | <b>SERVICE A1 IN 205D</b> | Parking lot: | <b>4510</b>                                     |
| Maintenance:                       | <b>OK</b>                 |              |   |
| Battery functioning:               | <b>Yes</b>                |              |   |
| Number of doors:                   | <b>5</b>                  |              |   |
| Number of seats:                   | <b>5</b>                  |              |   |
| Number head rests:                 | <b>5</b>                  |              |   |
| Rims summer:                       | <b>Aluminium</b>          |              |   |
| Category:                          | <b>Passenger Car</b>      |              |   |
| Oil level:                         | <b>OK</b>                 |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>                |              |   |

**Options**

|                                |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Seats electric F L                    |
| GPS storage                    | Seats electric F R                    |
| GPS storage                    | HD                                    |
| Windows electric F             | Central consol F                      |
| Windows electric R             | Luggage cover                         |
| Cruise Control                 | Front parking sensors                 |
| Steering wheel multifunctional | Rear parking sensors                  |
| Type of headlighting:          | <b>Headlighting Halogen</b>           |
| Type of GPS:                   | <b>GPS big screen color</b>           |
| Type of Lining:                | <b>Lining semi-artificial leather</b> |
| Type of climate control:       | <b>Autom climate control</b>          |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                     |       |                     |
| Winter tyres: | Fr.L.                            | <b>Kleber: 6 mm</b> | Fr.R. | <b>Kleber: 7 mm</b> |
|               | Re.L.                            | <b>Kleber: 5 mm</b> | Re.R. | <b>Kleber: 6 mm</b> |

**Assistance equipment**

|                    |            |      |            |
|--------------------|------------|------|------------|
| Spare tyre compact | <b>Yes</b> | Jack | <b>Yes</b> |
|--------------------|------------|------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 921,80 |
|-------------------|--------|

|  |       |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Repaired, P - Check 0,00



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display