



VOLKSWAGEN Passat: 1GKG424

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber: | WVWZZZ3CZEE117890 | Versionname: | PASSAT VAR Comfortline |
| First Registrationdate: | 3/03/2014 | Fiscalpower: | 136PK |
| Expertise Mileage: | 159823 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3122 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | VS | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Sun Roof electric |
| GPS storage | HD | Central consol F |
| GPS storage | | Luggage cover |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |
| Level control | | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--------------------------|---------------|
| Total cost ex VAT | 606,26 |
|--------------------------|---------------|

| | |
|--|---------------|
| Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 268,18 |
|--|---------------|





| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bonnet, Bump(s), LI - Repair and paint (complete) | 338,08 |
|---|--------|



| | |
|-------------------------------|------|
| Door R L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Wing R L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display