



VOLKSWAGEN Passat: 1GET549

Vinnnumber:	WVWZZZ3CZCE138487	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	20/01/2014	Fiscalpower:	
Expertise Mileage:	127301	Power Kw:	77
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2620
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/97 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2550,96
-------------------	---------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Seat cover F L, Stain, Cleaning 25,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Bad repair, Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Crack, Le - Replace and paint 651,00



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Seat cover F R, Stain, Cleaning 25,00



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 25,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display