



VOLVO XC60: 1ENS023			
Vinnumber:	YV1DZ31A1D2431738	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	1/02/2013	Fiscalpower:	
Expertise Mileage:	116127	Power Kw:	100
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1607
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	1178,16
Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	150,00





Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display