



VOLKSWAGEN GOLF VII: 1NCX056

Vinnnumber:	WVWZZZAUZGW180259	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	25/01/2016	Fiscalpower:	
Expertise Mileage:	51992	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2608
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT 2234,96

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08





Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F L, Scratch(es), It - Spot repair

115,56



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper corner R R, Scratch(es), It - Spot repair

115,56



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display