



VOLKSWAGEN Passat: 1FJK046

Vinnnumber:	WVWZZZ3CZEE027079	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	16/07/2013	Fiscalpower:	
Expertise Mileage:	178387	Power Kw:	77
Bodytype:	Break	Body color	Dark Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2730
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5,5 mm	Fr.R.	Uniroyal: 5,5 mm
	Re.L.	Uniroyal: 5,5 mm	Re.R.	Uniroyal: 5,5 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	791,28
-------------------	--------

Door F R, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	------

No pictures to display


Boot carpet, Stain, Cleaning	25,00
------------------------------	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 356,20



Windscreen, Repaired, Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Cleaning 25,00






Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R R, Bad repair, Paint 0,00



Rear window, Scratch(es), E - Replace 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

no pictures to display