



OPEL Movano 3500 LWB Med.High Roof: 067BAT

Vinnumber:	VN1F9C2L642129969	Versionname:	MOVANO 3500 B/F L3H2 100PK
First Registrationdate:	2/11/2009	Fiscalpower:	
Expertise Mileage:	122664	Power Kw:	74
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Central consol F	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	Tow bar fixed
Type of Lining:	Lining fabrics		

Limited Technical Inspection

Power steering:	Yes	Battery functioning:	Yes
Airco functioning:	NOT OK	Sound engine:	OK
Tires wear profile:	OK	Clutch test:	OK
Idle position:	OK	Wiper fluid level:	OK
Engine startingtime:	OK	Lighting:	OK
Exhaust gass:	OK	Wiperblades:	OK
Transmission:	OK		
Handbrake:	OK		

Degree of wear

	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Total cost ex VAT	2657,97
-------------------	---------

Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	362,02
---	--------



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Rearview mirror L complete, Broken, E - Replace 138,00



Rearview mirror R complete, Scratch(es), E - Replace 138,00



Sidewall RL (LCV), Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Roof, Damaged, Le - Replace and paint 1473,63



Bumper F R, Scratch(es), Smart repair 110,64



Door panel F R, Broken, P - Check 0,00



Bumper corner R R, Bump(s) and scratch(es), E - Replace 144,00



Tailgate lock, Not functioning (well), E - Replace 0,00



Bodywork, Not original part, Remove lettering	0,00
<i>No pictures to display</i>	
Interior, Stain, Acceptable	0,00
<i>No pictures to display</i>	