



VOLKSWAGEN PASSAT: 1GGO022

Vinnnumber:	WVWZZ3CZEE108102	Versionname:	VAR Comfortline BMT 105PK
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	99131	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4502
Maintenance:	OVER 14600 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunction			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm







Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	556,91
Door R L, Bump(s), LI - Repair and paint (complete)	366,35



Covering interior front pillar L, Stain, Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Repaired, P - Check		0,00
		
Rocker panel inner R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ceiling, Stain, Cleaning		0,00
		
Seat cover F L, Stain, Cleaning		25,00
		
Seat cover F R, Stain, Cleaning		0,00
		
Seat cover R, Stain, Cleaning		50,00
		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete)		115,56
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		