



VOLKSWAGEN GOLF VII: 1KST054

Vinnumber:	WVWZZZAUZFW241562	Versionname:	1.6 TDI 77KW BMT TRENDLINE
First Registrationdate:	24/06/2015	Fiscalpower:	
Expertise Mileage:	31313	Power Kw:	77
Bodytype:		Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4231
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar removable
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	NOT OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1323,54
Wiper Blade R, Damaged, E - Replace	35,00



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Rear window, Scratch(es), E - Replace 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Wiper Blade L, Damaged, E - Replace 35,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 301,68

