



VOLKSWAGEN TOURAN: 1GAZ661

Vinnumber:	WVGZZ1TZEW040875	Versionname:	TOURAN
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	109585	Power Kw:	
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	NOT OK
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	No	Battery functioning	Yes
Airco functioning	NOT OK	Sound engine	NOT OK
Tires wear profile	OK	Clutch test	NOT OK
Idle position	NOT OK	Wiper fluid level	OK
Engine startingtime	NOT OK	Lighting	OK
Exhaust gass	NOT OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1198,84

Alloy rim R L polished, Damaged, E - Replace 235,20



Reflector, Damaged, E - Replace	12,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Mirror side blinker R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Engine, Not functioning (well), I - Repair	0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Tailgate, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Bumper R, Bump(s) and scratch(es), Le - Replace and paint	651,00
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



