



AUDI A4: 1FXB590

Vinnumber:	WAUZZZ8K5EA076397	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	91468	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	24200KM 603J	Parking lot:	1626
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	DVD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	401,80
-------------------	---------------

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door F R, Bad repair, P - Check	0,00
---------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Windscreen, Repaired, P - Check 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bad repair, P - Check 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

