



VOLKSWAGEN Polo: XN9252			
Vinnumber:	WVWZZZ6RZEY080487	Versionname:	POLO BER Life 60PK
First Registrationdate:	19/12/2013	Fiscalpower:	
Expertise Mileage:	32161	Power Kw:	44
Bodytype:		Body color	Red
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2810
Number of doors	5		
Number of seats	5		
Number head rests	3		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	185/60/15/88 T Steel			
	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			584,56
Luggage space cover, Missing, E - Replace			192,00



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Headrest R L, Missing, E - Replace	48,00
------------------------------------	-------



Headrest R R, Missing, E - Replace	48,00
------------------------------------	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper corner R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------

