



**AUDI A4: 1FKT726**

|                         |                                |              |                            |
|-------------------------|--------------------------------|--------------|----------------------------|
| Vinnumber:              | <b>WAUZZZ8K4EA006888</b>       | Versionname: | <b>A4 AVANT TDie 136PK</b> |
| First Registrationdate: | <b>31/07/2013</b>              | Fiscalpower: |                            |
| Expertise Mileage:      | <b>60877</b>                   | Power Kw:    | <b>100</b>                 |
| Bodytype:               |                                | Body color:  | <b>Black</b>               |
| Gearbox:                | <b>MAN 6 VIT</b>               | Paint type:  | <b>Metalic</b>             |
| Transmission:           | <b>Front</b>                   | Rims summer: | <b>Aluminium</b>           |
| Fueltype:               | <b>Diesel</b>                  | Oil level:   | <b>OK</b>                  |
| Maintenance:            | <b>OK</b>                      | Parking lot: | <b>4619</b>                |
| Maintenance             | <b>SERVICE IN 21600KM 109D</b> |              |                            |
| Battery functioning:    | <b>Yes</b>                     |              |                            |
| Number of doors:        | <b>5</b>                       |              |                            |
| Number of seats:        | <b>5</b>                       |              |                            |
| Number head rests:      | <b>5</b>                       |              |                            |
| Rims summer:            | <b>Aluminium</b>               |              |                            |
| Category:               | <b>Passenger Car</b>           |              |                            |
| Oil level:              | <b>OK</b>                      |              |                            |

**Options**

|                                |                                 |
|--------------------------------|---------------------------------|
| Radio CD                       | Central consol F                |
| GPS storage                    | Luggage cover                   |
| GPS storage                    | <b>DVD</b> Rear parking sensors |
| Windows electric F             |                                 |
| Windows electric R             |                                 |
| Cruise Control                 |                                 |
| Steering wheel multifunctional |                                 |
| Radio multimedia               |                                 |
| Type of headlighting           | <b>Headlighting Halogen</b>     |
| Type of GPS                    | <b>GPS big screen color</b>     |
| Type of Lining                 | <b>Lining fabrics</b>           |
| Type of climate control        | <b>Autom climate control</b>    |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/96 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 7 mm</b> | Fr.R. | <b>Goodyear: 6 mm</b> |
|               | Re.L.                            | <b>Goodyear: 8 mm</b> | Re.R. | <b>Goodyear: 7 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |              |
|-------------------|--------------|
| Total cost ex VAT | <b>95,00</b> |
|-------------------|--------------|

|  |              |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|





Door R L, Bump(s), Acceptable 0,00

*No pictures to display*

Interior, No damage, Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*