


**TOYOTA GRAND PRIUS+: 1LRG943**

Vinnnumber:	<b>JTDZS3EU40J005016</b>	Versionname:	<b>1.8 VVT-I HYBRID ACTIVE</b>
First Registrationdate:	<b>13/11/2015</b>	Fiscalpower:	<b>AUTO</b>
Expertise Mileage:	<b>44384</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1709</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Alarm		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H Steel</b>			
Winter tyres:	Fr.L.	<b>Fulda: 6 mm</b>	Fr.R.	<b>Fulda: 6 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	281,20
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

No pictures to display

Bonnet, Damaged, Le - Replace and paint

69,40

