



VOLKSWAGEN Touran: 1FEX507

Vinnnumber:	WVGZZZ1TZDW107169	Versionname:	TOURAN Highline BMT Start/Stop 105PK
First Registrationdate:	11/06/2013	Fiscalpower:	
Expertise Mileage:	161673	Power Kw:	77
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1413
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunction			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2435,86
-------------------	----------------

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Door R R, Scratch(es), Acceptable 0,00

No pictures to display


Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Hole, E - Replace 50,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Window R R door, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Window R L door, Scratch(es), E - Replace 133,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting 63,00



Rear window, Scratch(es), E - Replace 370,00





Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Window F L door, Scratch(es), E - Replace 133,00

