



VOLVO V40: 1EOE292			
Vinnumber:	YV1MV8481D2037639	Versionname:	V40 D2 Base 115PK
First Registrationdate:	5/02/2013	Fiscalpower:	
Expertise Mileage:	163128	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4629
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		


Degree of wear				
	205/55/16/94 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1446,73
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80




Alloy rim R.L. Scratch(es), LI - Repair and paint (complete)			95,00
--	--	--	--------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 50,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Interior, Dirty, Cleaning 50,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display