



VOLVO V60: 1GIL156			
Vinnnumber:	YV1FW31A1E1196248	Versionname:	V60 BRE D3 Kinetic 136PK
First Registrationdate:	17/02/2014	Fiscalpower:	
Expertise Mileage:	86270	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2215
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering:	Yes	Battery functioning:	Yes
Airco functioning:	OK	Sound engine:	OK
Tires wear profile:	OK	Clutch test:	OK
Idle position:	OK	Wiper fluid level:	OK
Engine startingtime:	OK	Lighting:	OK
Exhaust gass:	OK	Wiperblades:	OK
Transmission:	OK		
Handbrake:	OK		

Degree of wear				
	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment			
Repair kit:	Yes	Compressor:	Yes
Total cost ex VAT:			431,98
Wing F R, Scratch(es), LI - Repair and paint (complete):			220,18



Front bumper, Scratch(es), LI - Repair and paint (complete):	211,80
--	---------------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display