



BMW 3 BERLINE: 1PTR495

Vinnumber:	WBA3E11060J709770	Versionname:	2.0 320D EFFICIENTDYN. (120KW) BERLINE
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	126461	Power Kw:	120
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	7000KM OF 12:2018	Parking lot	1431
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1993,54
-------------------	---------

Wing R L, Scratch(es), 67 - Polish	55,19
------------------------------------	-------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R L, Bump(s), PDR - Knock out without painting 63,00



Door frame R L, Scratch(es), It - Spot repair 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Seat cover R, Stain, Cleaning 25,00



Wing F L, Chemical polution, LI - Repair and paint (complete) 220,18



Seat cover F L, Stain, Cleaning 25,00



Rearview mirror housing L, Broken, Le - Replace and paint 179,55



Seat cover F R, Stain, Cleaning

25,00

