



BMW 1: 1GDS853

Vinnnumber:	WBA1C91000J519815	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	9/01/2014	Fiscalpower:	
Expertise Mileage:	62714	Power Kw:	85
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	- 10.000KM	Parking lot:	4819
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	HD Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	NOT OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1658,30
-------------------	----------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------

No pictures to display

Door F L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Rearview mirror glass L, Broken, E - Replace 18,00



Ignition key, Missing, E - Replace 150,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35

Door L R, Scratch(es), LI - Repair and paint (complete) 310,00



Interior, Stain, Cleaning 50,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

