



BMW 1: 1GDN867

Vinnumber:	WBA1C91080J519903	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	8/01/2014	Fiscalpower:	
Expertise Mileage:	134695	Power Kw:	85
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 6000KM 11 2018	Parking lot:	4727
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Power steering:	Yes	Battery functioning:	Yes
Airco functioning:	OK	Sound engine:	OK
Tires wear profile:	OK	Clutch test:	OK
Idle position:	OK	Wiper fluid level:	OK
Engine startingtime:	OK	Lighting:	OK
Exhaust gass:	OK	Wiperblades:	OK
Transmission:	OK		
Handbrake:	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Total cost ex VAT:	58,80
--------------------	--------------

Alloy rim F L, Scratch(es), Acceptable:	0,00
---	-------------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair:	58,80
---	--------------



Bonnet, Chemical polution, Acceptable:	0,00
--	-------------



Interior, No damage, Acceptable

0,00

No pictures to display