



BMW 3 TOURING: 1KAF594

Vinnnumber:	WBA3K11010F838513	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	18/03/2015	Fiscalpower:	
Expertise Mileage:	67739	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:		Oil level:	NOT OK
Battery functioning:	No	Parking lot:	DEP 2000 489
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		

Options

Type of headlighting:	Headlighting Halogen	Front parking sensors:	
Type of Lining:	Lining leather	Rear parking sensors:	

Limited Technical Inspection

Power steering:	No	Battery functioning:	No
Airco functioning:	NOT OK	Sound engine:	NOT OK
Tires wear profile:	NOT OK	Clutch test:	NOT OK
Idle position:	NOT OK	Wiper fluid level:	NOT OK
Engine startingtime:	NOT OK	Lighting:	NOT OK
Exhaust gass:	NOT OK	Wiperblades:	NOT OK
Transmission:	NOT OK		
Handbrake:	NOT OK		

Degree of wear

	0/0/0/0 A LightMetal			
Summer tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	N.D.	Re.R.	N.D.

Assistance equipment

Total cost ex VAT	0,00
Bodywork, Accident, No repair	0,00



