


**BMW 3: 1FWF425**

Vinnnumber:	<b>WBA3E11000J709697</b>	Versionname:	<b>3 BER 320d Eff.Dynamics Ed.163PK</b>
First Registrationdate:	<b>15/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>63874</b>	Power Kw:	<b>120</b>
Bodytype:		Body color	<b>ARGENT</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Silver</b>
Transmission:	<b>Back</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Battery functioning	<b>Yes</b>	Oil level	<b>OK</b>
Number of doors	<b>4</b>	Parking lot	<b>4612</b>
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 WINTER H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

**Total cost ex VAT** 120,56

**Seat cover R, Missing, E - Replace** 5,00

**Alloy rim R R, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Alloy rim R L, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Door F L, Bump(s), Acceptable** 0,00

<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), It - Spot repair		115,56
Roof, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel F L, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		