



MERCEDES B: 1EPR434			
Vinnumber:	WDD2462001J146719	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	18/02/2013	Fiscalpower:	
Expertise Mileage:	71728	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1507
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	2501,18
Wheel cover F R, Scratch(es), E - Replace	30,00



Roof pillar R, Chemical polution, LI - Repair and paint (complete)	220,18
--	---------------



Door F R, Chemical polution, LI - Repair and paint (complete) 318,35



Rearview mirror housing L, Chemical polution, LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68



Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Door R R, Chemical polution, LI - Repair and paint (complete) 318,35



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Chemical polution, LI - Repair and paint (complete) 115,56



Windscreen, Stone chip(s), Acceptable 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Interior, Dirty, Cleaning

50,00



Wheel cover R R, Scratch(es), E - Replace

30,00

