


FORD Grand C-Max: 1EAZ722

Vinnnumber:	WF0HXXWPBHCL31329	Versionname:	GR.C-MAX Trend St/St
First Registrationdate:	8/10/2012	Fiscalpower:	95PK
Expertise Mileage:	135525	Power Kw:	70
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4233
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

215/55/16/93 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Compressor	Yes
Repair kit	Yes		

Total cost ex VAT	1326,95
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00





Tailgate, Scratch(es), Acceptable 0,00

No pictures to display


Roof pillar L, Bump(s), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 125,00



Door R L, Bump(s), LI - Repair and paint (complete) 414,35



Mirror side blinker R, Missing, E - Replace 69,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Roof pillar R, Bump(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Wing F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Spoiler F L, Scratch(es), E - Replace	42,00
---------------------------------------	-------

