




|                            |                          |              |   |
|----------------------------|--------------------------|--------------|---|
| <b>MERCEDES C: 1EDK140</b> |                          |              |   |
| Vinnumber:                 | <b>WDD2042001G031252</b> | Versionname: | <b>C BRE 180 CDI BlueEFF. S&amp;S 120PK</b> |
| First Registrationdate:    | <b>29/10/2012</b>        | Fiscalpower: |   |
| Expertise Mileage:         | <b>153450</b>            | Power Kw:    | <b>88</b>                                   |
| Bodytype:                  | <b>Break</b>             | Body color:  | <b>Grey</b>                                 |
| Gearbox:                   | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                              |
| Transmission:              |                          | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:                  | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                   |
| Battery functioning:       | <b>Yes</b>               | Parking lot: | <b>4112</b>                                 |
| Number of doors:           | <b>5</b>                 |              |   |
| Number of seats:           | <b>5</b>                 |              |   |
| Number head rests:         | <b>5</b>                 |              |   |
| Rims summer:               | <b>Aluminium</b>         |              |   |
| Category:                  | <b>Passenger Car</b>     |              |   |
| Oil level:                 | <b>OK</b>                |              |   |

|                                |                              |                  |                      |
|--------------------------------|------------------------------|------------------|----------------------|
| <b>Options</b>                 |                              |                  |                      |
| Radio CD                       |                              | Central consol F |                      |
| Windows electric F             |                              | Luggage cover    |                      |
| Windows electric R             |                              | Type of Tow bar  | <b>Tow bar fixed</b> |
| Cruise Control                 |                              |                  |                      |
| Steering wheel multifunctional |                              |                  |                      |
| Radio multimedia               |                              |                  |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                  |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                  |                      |
| Type of climate control        | <b>Autom climate control</b> |                  |                      |

|                                     |            |                     |            |
|-------------------------------------|------------|---------------------|------------|
| <b>Limited Technical Inspection</b> |            |                     |            |
| Power steering                      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning                   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile                  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position                       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission                        | <b>OK</b>  |                     |            |
| Handbrake                           | <b>OK</b>  |                     |            |

|                       |                                  |                          |       |                          |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                  |                          |       |                          |
|                       | <b>205/55/16/91 H LightMetal</b> |                          |       |                          |
| Winter tyres:         | Fr.L.                            | <b>BF Goodrich: 5 mm</b> | Fr.R. | <b>BF Goodrich: 5 mm</b> |
|                       | Re.L.                            | <b>BF Goodrich: 6 mm</b> | Re.R. | <b>BF Goodrich: 6 mm</b> |

|                                       |            |      |               |
|---------------------------------------|------------|------|---------------|
| <b>Assistance equipment</b>           |            |      |               |
| Spare wheel                           | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT                     |            |      | <b>680,00</b> |
| Rear window, Scratch(es), E - Replace |            |      | <b>370,00</b> |



|                                 |              |
|---------------------------------|--------------|
| Seat cover R R, Dirty, Cleaning | <b>25,00</b> |
|---------------------------------|--------------|



|  |       |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|  |      |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|  |       |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|                                       |      |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

*No pictures to display*