



CITROEN C4 PICASSO: 1GKH396

Vinnumber:	VF73A9HC8EJ564542	Versionname:	
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	127052	Power Kw:	85
Bodytype:	MPV	Body color:	Red
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4701
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Other: 6 mm	Fr.R.	Other: 6 mm
	Re.L.	Hankook: 7 mm	Re.R.	Hankook: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1807,58

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Crack, E - Replace 487,20



Interior, Stain, Cleaning 100,00



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper corner R L, Unclassped, N - Mount/Dismount 0,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

Winggate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Bump(s), LI - Repair and paint (complete) 406,50



Reflector, Broken, E - Replace 59,00



Door R L, Bump(s), PDR - Knock out without painting 63,00

