


FORD S Max: 1GMV490

Vinnnumber:	WF0SXXGBWSEY29270	Versionname:	5-MAX Titanium Style DPF
First Registrationdate:	13/03/2014	Fiscalpower:	136PK
Expertise Mileage:	109445	Power Kw:	100
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4203
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	SD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining leather	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	807,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), PDR - Knock out without painting	63,00



Luggage space cover, Missing, E - Replace	288,00
---	--------



Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Headlight L, Broken, E - Replace	456,00
----------------------------------	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display