



NISSAN Qashqai: 1DQV585

Vinnnumber:	SJNJEAJ10U7126377	Versionname:	QASHQAI+2 2WD Tekna+N.Conn.St/St 130PK
First Registrationdate:	26/07/2012	Fiscalpower:	
Expertise Mileage:	172933	Power Kw:	96
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3331
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Panoramic roof
GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/60/17/96 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2164,48
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Cleaning 50,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 487,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F R, Stain, Cleaning 25,00



Rearview mirror housing R, Bad repair, Paint 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display


Trunk lid covering R, Broken, E - Replace 99,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Rocker panel inner F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rearview mirror housing L, Bad repair, Paint	0,00
--	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display