



FORD Grand C-Max: 1EEW625

Vinnnumber:	WF0HXXWPBHCY42820	Versionname:	GR.C-MAX Trend St/St
First Registrationdate:	12/11/2012	Fiscalpower:	115PK
Expertise Mileage:	165947	Power Kw:	85
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3401
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
GPS storage	Rear parking sensors
GPS storage	SD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		


Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 4,5 mm	Re.R.	Michelin: 4,5 mm





















Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1174,98
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00




Rear spoiler, Stain, Acceptable	0,00
---------------------------------	------

		Interior, Stain, Cleaning	25,00	
		Wing R R, Bump(s), Acceptable	0,00	
<i>No pictures to display</i>				
Roof, Stain, Acceptable			0,00	
<i>No pictures to display</i>				
Wing F L, Bump(s), PDR - Knock out without painting			63,00	
			Roof pillar L, Stain, Acceptable	0,00
		Bonnet, Stone chip(s), Acceptable	0,00	
<i>No pictures to display</i>				
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00	
				
			Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Rear window, Scratch(es), E - Replace			370,00	
				
			Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
			Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Roof pillar R, Stain, Acceptable 0,00

