




FORD S Max: 1BOL919			
Vinnumber:	WF0SXXGBWSBY32186	Versionname:	S-MAX Econetic Trend St&St DPF 115PK
First Registrationdate:	18/07/2011	Fiscalpower:	
Expertise Mileage:	180371	Power Kw:	85
Bodytype:	MPV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 6 mm	Re.R.	BF Goodrich: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			929,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Protection plate M, Deformed, E - Replace	74,00
--	--------------



Boot carpet, Damaged, E - Replace	120,00
--	---------------



Roof, Bump(s), LI - Repair and paint (complete)	577,80
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------

