



OPEL Astra: 1EZL394

Vinnumber:	WOLPE8EW4D8049350	Versionname:	ASTRA BRE ecoFLEX Cosmo St/St 110PK
First Registrationdate:	29/04/2013	Fiscalpower:	
Expertise Mileage:	88380	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4414
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm


Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	591,36
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door F L, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Front bumper, Scratch(es), It - Spot repair 115,56



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Rear window, Scratch(es), E - Replace 0,00



Windscreen, Scratch(es), E - Replace 0,00



Bumper grille, Crack, E - Replace 74,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

