



OPEL Astra: 1EES297			
Vinnumber:	W0LPC6DA5D1023056	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	9/11/2012	Fiscalpower:	
Expertise Mileage:	120629	Power Kw:	70
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4723
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control


Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm


Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1233,58
Bumper moulding R, Damaged, E - Replace			38,40



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

