


OPEL Meriva: 1ERW850

Vinnnumber:	WOLSH9EC0D4096346	Versionname:	MERIVA Cosmo St/St
First Registrationdate:	5/03/2013	Fiscalpower:	100PK
Expertise Mileage:	69806	Power Kw:	74
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2703
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	74,00
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Crack, E - Replace	74,00



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display