



OPEL Insignia: 1EJR747			
Vinnumber:	W0LGM8EL3D1044139	Versionname:	INSIGNIA BRE ecoFL.Edit.150Ys DPF 130PK
First Registrationdate:	2/01/2013	Expertise Mileage:	179353
Bodytype:	Break	Fiscalpower:	96
Gearbox:	MAN 6 VIT	Power Kw:	96
Transmission:	Front	Body color:	Purple
Fueltype:	Diesel	Paint type:	Metalic
Battery functioning:	Yes	Rims summer:	Steel
Number of doors:	5	Oil level:	OK
Number of seats:	5	Parking lot:	2610
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear			
Winter tyres:	225/55/17/101 V Steel		
	Fr.L.	Fr.R.	
	Semperit: 6 mm	Semperit: 6 mm	
	Re.L.	Re.R.	
	Bridgestone: 5 mm	Bridgestone: 5 mm	

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT 1306,90

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Waterinfiltration, E - Replace 114,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

no pictures to display


Sunblind R, Damaged, E - Replace 150,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper moulding R, Strained , E - Replace 14,40



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display


Ignition key, Damaged, E - Replace 150,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display


Roof, Bad repair, Acceptable 0,00



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display