



RENAULT Kangoo: 1ENU570

| | | | |
|-------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | VF1KW24B548563123 | Versionname: | KANGOO Authentique FAP 75PK |
| First Registrationdate: | 1/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 117015 | Power Kw: | 55 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2233 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|----------------------|-----------------------------|
| Radio CD | Luggage cover |
| Windows electric F | |
| Type of headlighting | Headlighting Halogen |
| Type of Lining | Lining fabrics |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 T Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|---|---------|
| Total cost ex VAT | 1083,00 |
| Wheel cover F R, Scratch(es), E - Replace | 22,50 |



| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 158,85 |
|---|--------|



| | |
|---------------------------|------|
| Bonnet, Bad repair, Paint | 0,00 |
|---------------------------|------|



| | |
|-------------------------------|------|
| Door R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|---|--------|
| Roof, Chemical polution, LI - Repair and paint (complete) | 361,13 |
|---|--------|



| | |
|---|--------|
| Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 238,76 |
|---|--------|



| | |
|---|-------|
| Door F R, Bump(s), PDR - Knock out without painting | 63,00 |
|---|-------|



| | |
|---|--------|
| Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 238,76 |
|---|--------|

