



RENAULT Grand Scenic: 1GTF477

Vinnumber:	VF1JZ14M650240094	Versionname:	GRAND SCENIC Business Spl.110PK
First Registrationdate:	23/04/2014	Fiscalpower:	
Expertise Mileage:	115125	Power Kw:	81
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3402
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Goodyear: 8 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2212,94

Interior, Stain, Cleaning 125,00





Front bumper, Crack, Le - Replace and paint 735,00



Windscreen, Scratch(es), E - Replace 0,00



Interior, Smell, Ozone treatment 152,58



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting 111,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F R, Damaged, E - Replace 138,00



Wing moulding F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), PDR - Knock out without painting 159,00



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 187,56







Luggage space cover, Missing, E - Replace 240,00



Rear window, Scratch(es), E - Replace 0,00



Sidewall panel RR, Scratch(es), E - Replace 123,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00

