



RENAULT Scenic: 1GKI333			
Vinnnumber:	VF1JZ14K650186503	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	149366	Power Kw:	81
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2609
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	1204,82
Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56




Interior, Dirty, Cleaning	100,00
---------------------------	---------------



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), PDR - Knock out without painting 82,80





Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 30,00



Wheel cover R L, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), E - Replace	30,00
	
Roof pillar R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
	
Roof pillar L, Bump(s), PDR - Knock out without painting	82,80
