


SKODA OCTAVIA COMBI: 1KCS549

Vinnumber:	TMBLG7NE7F0204440	Versionname:	1.6 CRTDI GREENTEC AMBITION
First Registrationdate:	1/04/2015	Fiscalpower:	
Expertise Mileage:	164298	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4630
Maintenance:	IN 17200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	NOT OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	956,20
-------------------	--------

Wheel cover R R, Scratch(es), Acceptable	0,00
------------------------------------------	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
------------------------------------------	------





Engine, Not functioning (well), P - Check 0,00



Seat cover F L, Stain, Cleaning 25,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 454,50



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Outer valance R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Switch window control F L, Not functioning (well), P - Check 0,00




Interior, Smell, Ozone treatment 152,58



Floor covering F L, Burned, Smart repair 112,32





Seat cover F R, Stain, Acceptable

0,00

No pictures to display