



RENAULT Scenic: 1GKF502			
Vinnnumber:	<b>VF1JZ14K650186506</b>	Versionname:	<b>SCENIC Energy Life 110PK</b>
First Registrationdate:	<b>3/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>87252</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1108</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options	
Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
Summer tyres:	205/60/16/92 H Steel			
	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Spare wheel	<b>Yes</b>

Total cost ex VAT	1071,68
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

Ignition key, Missing, E - Replace	150,00
No pictures to display	
Interior, Dirty, Cleaning	100,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
	
	