

SKODA Octavia: 1BOP777

Vinnnumber:	TMBHT21Z7C2018717	Versionname:	OCTAVIA COMBI Ambiente DPF 105PK
First Registrationdate:	19/07/2011	Fiscalpower:	
Expertise Mileage:	135434	Power Kw:	77
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1511
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1273,84
-------------------	---------

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------


No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), It - Spot repair 115,56



Interior, Dirty, Cleaning 100,00



Daytime running lights L, Unclassped, N - Mount/Dismount 48,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

