



VOLVO XC60: 1FPE674

Vinnnumber:	YV1DZ8756E2533492	Versionname:	XC60 D4 4WD Kinetic Geartr.163PK Aut.
First Registrationdate:	12/09/2013	Fiscalpower:	
Expertise Mileage:	172079	Power Kw:	120
Bodytype:	SUV	Body color:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	235/60/18/107 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Jack	Yes
------------	------------	------	------------

Total cost ex VAT	636,18
-------------------	--------

Alloy rim R L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Door moulding Lower F R, Scratch(es), E - Replace	0,00
---------------------------------------------------	------



Roof pillar L, Bump(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	0,00
---------------------------------------------------------	------




Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 0,00

