



VOLKSWAGEN Crafter 35 MWB hoog dak: 037APJ

Vinnumber:	WV1ZZZ2EZ96034736	Versionname:	CRAFTER 35 B/F MWB HR
First Registrationdate:	20/05/2009	Fiscalpower:	88pk
Expertise Mileage:	110072	Power Kw:	65
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	235/65/16/113 R Steel			
Winter tyres:	Fr.L.	Kleber: 8 mm	Fr.R.	Kleber: 8 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	No
-------------	-----------

Total cost ex VAT	2162,08
-------------------	---------

Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rearview mirror glass R, Broken, E - Replace	13,50
--	-------



Trunk door R L, Bump(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Front bumper, Damaged, E - Replace	398,40
------------------------------------	--------



Rearview mirror housing L, Damaged, E - Replace 74,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door panel R, Damaged, I - Repair 48,00



Spare wheel, Missing, E - Replace 153,60

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door moulding Lower R L, Damaged, E - Replace 91,50



Interior, Dirty, Cleaning 50,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76





Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Seat cover F L, Worn, Acceptable 0,00



Door moulding Lower R L, Damaged, E - Replace 91,50



Wing R R, Rust, LI - Repair and paint (complete) 231,15

