


**RENAULT Scenic: 1GBA346**

Vinnnumber:	<b>VF1JZ14J650211346</b>	Versionname:	<b>SCENIC XMOD Energy Zen 110PK</b>
First Registrationdate:	<b>11/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>82874</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3332</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage	<b>SD</b>	Sun Roof electric
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunction		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather and alcantara</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/60/17/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 3 mm</b>	Fr.R.	<b>Fulda: 3 mm</b>
	Re.L.	<b>Fulda: 3 mm</b>	Re.R.	<b>Fulda: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	<b>1174,67</b>
-------------------	----------------

Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

*No pictures to display*


Protection plate M, Tear, E - Replace	<b>74,00</b>
---------------------------------------	--------------




Bumper corner R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Rear window, Scratch(es), E - Replace	<b>370,00</b>
---------------------------------------	---------------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Front bumper, Scratch(es), Smart repair 110,64



Tailgate, Chemical pollution, LI - Repair and paint (complete) 301,68

