


RENAULT Scenic: 1GIE630

Vinnumber:	VF1JZ500E50328689	Versionname:	SCENIC Bose Ed.EDC 110PK Aut.
First Registrationdate:	14/02/2014	Fiscalpower:	
Expertise Mileage:	16096	Power Kw:	81
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4707
Maintenance:	DANS 10 JOURS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection


Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear


	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			190,00
Seat cover F L, Deformed, Acceptable			0,00
<i>No pictures to display</i>			
Bumper F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper corner R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear spoiler, Chemical polution, Acceptable			0,00



Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------






Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display

Roof, Chemical polution, Acceptable	0,00
-------------------------------------	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display

Bumper F M, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Daytime running lights R, Waterinfiltration, P - Check	0,00
--	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display