



VOLKSWAGEN Golf: 1HNF486			
Vinnumber:	WVWZZZAUZFP531912	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	27/08/2014	Fiscalpower:	
Expertise Mileage:	137254	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			589,18
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80



Rearview mirror housing R, Scratch(es), Paint	50,00
--	--------------



Seat cover R L, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper grille, Broken, E - Replace	109,00
------------------------------------	--------



Door frame F L, Scratch(es), 67 - Polish	55,19
--	-------



Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Seat cover F L, Stain, Cleaning	15,00
---------------------------------	-------



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Door frame R L, Scratch(es), 67 - Polish	55,19
--	-------

