



**VOLKSWAGEN Crafter 35 MWB hoog dak: 034APJ**

Vinnumber:	<b>WV1ZZZ2EZ96033915</b>	Versionname:	<b>CRAFTER 35 B/F MWB HR</b>
First Registrationdate:	<b>20/05/2009</b>	Fiscalpower:	<b>88pk</b>
Expertise Mileage:	<b>165366</b>	Power Kw:	<b>65</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2604</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Cruise Control		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>235/65/16/115 R LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>


**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>636,72</b>
Wing R R, Bad repair, Paint	<b>0,00</b>



Front bumper, Damaged, Smart repair	<b>110,64</b>
-------------------------------------	---------------



Seat cover F L, Worn, Acceptable	<b>0,00</b>
----------------------------------	-------------

*No pictures to display*

Sliding door R, Bump(s), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------



Wing R L, Scratch(es), It - Spot repair	115,56
---	--------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Mirror side blinker R, Damaged, E - Replace	28,50
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Bad repair, Paint	0,00
-----------------------------	------

